



## CARVING ON A LATHE

### **ABSOLUTELY POSITIVELY *MUST* USE A SAFETY DRIVE**

*THIS AND ONLY THIS WILL PROVIDE SAFETY*

E.G., Robust "CUP DRIVE" or Oneway "SAFE DRIVER"



UNLIKE ALMOST ANY OTHER TYPE OF TURNING

WORK PIECE ***MUST*** BE ABLE TO ***SLIP*** BETWEEN CENTERS if there is a catch

NO SPURS – NOT 2 – NOT 4 – NONE!!!

NO STEB CENTER

NO CUP DRIVE WITH SCALLOPS

**ONLY A SAFETY DRIVE – SMALL CUP WITH CENTRAL PIN !!!**

Pin is necessary for mounting, security, and repeating mounts

IF THE WORK PIECE CANNOT SLIP WHEN THERE IS CATCH – IT IS NOT SAFE